



10/18/00

UTILITY PATENT APPLICATION TRANSMITTAL

(Only for new nonprovisional applications under 37 CFR 1.53(b))

Attorney Docket No. 1095.1139/JDH

First Named Inventor or Application Identifier:

Makoto FUJIEDA

Express Mail Label No.

 10/18/00
 10951139
 12

10/18/00

APPLICATION ELEMENTS <i>See MPEP chapter 600 concerning utility patent application contents.</i>		ADDRESS TO: Assistant Commissioner for Patents Box Patent Application Washington, DC 20231
<p>1. <input checked="" type="checkbox"/> Fee Transmittal Form</p> <p>2. <input checked="" type="checkbox"/> Specification, Claims & Abstract [Total Pages: <u>39</u>]</p> <p>3. <input checked="" type="checkbox"/> Drawing(s) (35 USC 113) [Total Sheets: <u>39</u>]</p> <p>4. <input checked="" type="checkbox"/> Oath or Declaration [Total Pages: <u>3</u>]</p> <p>a. <input checked="" type="checkbox"/> Newly executed (original or copy)</p> <p>b. <input type="checkbox"/> Copy from a prior application (37 CFR 1.63(d)) (for continuation/divisional with Box 17 completed)</p> <p>i. <input type="checkbox"/> <u>DELETION OF INVENTOR(S)</u> Signed statement attached deleting inventor(s) named in the prior application, see 37 CFR 1.63(d)(2) and 1.33(b).</p> <p>5. <input type="checkbox"/> Incorporation by Reference (usable if Box 4b is checked) The entire disclosure of the prior application, from which a copy of the oath or declaration is supplied under Box 4b, is considered as being part of the disclosure of the accompanying application and is hereby incorporated by reference therein.</p> <p>6. <input type="checkbox"/> Microfiche Computer Program (Appendix)</p> <p>7. <input type="checkbox"/> Nucleotide and/or Amino Acid Sequence Submission (<i>if applicable, all necessary</i>)</p> <p>a. <input type="checkbox"/> Computer Readable Copy</p> <p>b. <input type="checkbox"/> Paper Copy (identical to computer copy)</p> <p>c. <input type="checkbox"/> Statement verifying identity of above copies</p>		
ACCOMPANYING APPLICATION PARTS		
<p>8. <input checked="" type="checkbox"/> Assignment Papers (cover sheet & document(s))</p> <p>9. <input type="checkbox"/> 37 CFR 3.73(b) Statement (<i>when there is an assignee</i>) <input type="checkbox"/> Power of Attorney</p> <p>10. <input type="checkbox"/> English Translation Document (<i>if applicable</i>)</p> <p>11. <input type="checkbox"/> Information Disclosure Statement (IDS)/PTO-1449 <input type="checkbox"/> Copies of IDS Citations</p> <p>12. <input type="checkbox"/> Preliminary Amendment</p> <p>13. <input checked="" type="checkbox"/> Return Receipt Postcard (MPEP 503) (<i>Should be specifically itemized</i>)</p> <p>14. <input type="checkbox"/> Small Entity Statement(s) <input type="checkbox"/> Statement filed in prior application, status still proper and desired.</p> <p>15. <input checked="" type="checkbox"/> Certified Copy of Priority Document(s) (<i>if foreign priority is claimed</i>)</p> <p>16. <input type="checkbox"/> Other:</p>		
<p>17. If a CONTINUING APPLICATION, check appropriate box and supply the requisite information:</p> <p><input type="checkbox"/> Continuation <input type="checkbox"/> Divisional <input type="checkbox"/> Continuation-in-part (CIP) of prior application No: <u> / </u></p>		
<p>18. CORRESPONDENCE ADDRESS</p>		

 21171
 PATENT TRADEMARK OFFICE

Staas & Halsey

**NEW APPLICATION
FEE TRANSMITTAL**

		Attorney Docket No.	1095.1139/JDH
		Application Number	TO BE ASSIGNED
		Filing Date	October 16, 2000
AMOUNT ENCLOSED	\$750.00	First Named Inventor	Makoto FUJIEDA

FEE CALCULATION (fees effective 12/29/99)

CLAIMS	(1) FOR	(2) NUMBER FILED	(3) NUMBER EXTRA	(4) RATE	(5) CALCULATIONS
	TOTAL CLAIMS	9 - 20 =	0	X \$ 18.00 =	\$ 0.00
	INDEPENDENT CLAIMS	2 - 3 =	0	X \$ 80.00 =	0.00
	MULTIPLE DEPENDENT CLAIMS (any number; if applicable)			+ \$260.00 =	0.00
				BASIC FILING FEE	710.00
				Total of above Calculations =	\$ 710.00
	Surcharge for late filing fee, Statement or Power of Attorney (\$130.00)				0.00
	Reduction by 50% for filing by small entity (37 CFR 1.9, 1.27 & 1.28).				- 0.00
				TOTAL FILING FEE =	\$ 710.00
	Surcharge for filing non-English language application (\$130.00; 37 CFR 1.52(d))				0.00
	Recordation of Assignment (\$40.00; 37 CFR 1.21(h)(1))				40.00
				TOTAL FEES DUE =	\$ 750.00

METHOD OF PAYMENT

Check enclosed as payment.
 Charge "TOTAL FEES DUE" to the Deposit Account No., below.
 No payment is enclosed and no charges to the Deposit Account are authorized at this time.

GENERAL AUTHORIZATION

If the above-noted "AMOUNT ENCLOSED" is not correct, the Commissioner is hereby authorized to credit any overpayment or charge any additional fees necessary to:

Deposit Account No.

19-3935

Deposit Account Name

STAAS & HALSEY LLP

The Commissioner is also authorized to credit any overpayments or charge any additional fees required under 37 CFR 1.16 (filing fees) or 37 CFR 1.17 (processing fees) during the prosecution of this application, including any related application(s) claiming benefit hereof pursuant to 35 USC § 120 (e.g., continuations/divisionals/CIPs under 37 CFR 1.53(b) and/or continuations/divisionals/CPAs under 37 CFR 1.53(d)) to maintain pendency hereof or of any such related application.

SUBMITTED BY: STAAS & HALSEY LLP

Typed Name	James D. Halsey, Jr.	Reg. No.	22,729
Signature		Date	October 16, 2000

THREE-DIMENSIONAL MODEL MANAGEMENT SYSTEM

BACKGROUND OF THE INVENTION

(1) Field of the Invention

5 The present invention relates to a three-dimensional model management system, and more particularly, to a three-dimensional model management system for managing three-dimensional models constituted by multiple parts.

(2) Description of the Related Art

10 With recent advance in three-dimensional CAD (Computer Aided Design), there has been an increasing tendency to produce necessary drawings, parts lists, etc. from three-dimensional models of products created beforehand on a computer.

15 Simultaneously, PDM (Product Data Management) has also been spreading in which all data relating to product development is managed in an integrated manner for effective use of data and higher efficiency of design work etc.

Recently, therefore, there is a growing tendency
20 to harmonize three-dimensional CAD with PDM, thereby to make
more practical use of data through the course of process
from design to manufacture.

Meanwhile, parts defined in CAD and parts defined
in PDM are often not in one-to-one correspondence. For
25 example, when drawing a figure by CAD, a dummy part which
actually does not exist is sometimes used in order to show
the relationship of engagement between parts. Thus, if a

parts list is created by PDM based on a three-dimensional model including such a dummy part, a problem arises in that an unnecessary part is also shown.

Also, data created by CAD often has a data structure specific to the CAD. For example, when drawing a part with a plurality of identical portions or segments, it is often the case that a segment is drawn, copied, and modified by rotation etc., to obtain a desired part by finally combining the segments. In such cases, however, since the segments are registered as separate parts, a problem arises in that there is no one-to-one correspondence between the contents of parts list and actual parts. One such specific example is shown in FIG. 35. The illustrated example is constituted by cylindrical parts a and c, and a regular hexahedron b. To draw a three-dimensional model like this by means of CAD, first, the cylindrical part a is drawn as shown in FIG. 36, for example, and the part a is copied and rotated clockwise by 90 degrees to obtain the part b. Then, the parts a and b are joined to the part c to obtain the three-dimensional model shown in FIG. 35. In this case, even if these three parts actually constitute a single part, for example, they are managed by CAD as three separate parts. Consequently, when a parts list is generated, parts that actually do not exist are output.

As another example of drawing a figure by CAD, it is often the case that using a specific surface or the like of a certain part as a reference, another part is made to

engage with the part. In such cases, the reference part and the engaged part are often treated as high and low hierarchical levels, respectively, for convenience' sake. Since, however, which part is engaged by using which part as 5 a reference part can vary depending upon the designer, there often arises a discrepancy between the hierarchical structure at the stage of design and that of actual parts. In such cases, when the data is displayed in the form of parts list, an unnecessary hierarchical structure is 10 disadvantageously generated. One such specific example is shown in FIG. 37. In this example, hexahedrons A and B are engaged with each other and a bar C is inserted into rectangular holes in the central portions of the hexahedrons, as shown in FIG. 38. When constructing such a three- 15 dimensional model, for example, the hexahedron B is engaged with the hexahedron A as the reference part, and then using the hexahedron A as the reference part, the bar C is inserted. FIG. 39(A) shows a hierarchical structure of the parts derived in this case. Specifically, the hexahedron A 20 is at the highest hierarchical level while the hexahedron B and the bar C are classified as subordinate thereto. In the case where the bar C is inserted using the hexahedron B as the reference part, a hierarchical structure shown in FIG. 39(B) is derived. Thus, the hierarchical structure varies 25 depending upon how the parts are combined, and accordingly, when a parts list is generated, an unnecessary hierarchical structure may possibly be shown, making the structure

complicated.

Further, drawings etc. created by CAD sometimes require supervisor's approval. Conventionally, however, to enable such a supervisor to view drawings prepared by CAD, 5 the drawings must be printed out or the necessary CAD software must be installed in the supervisor's terminal, but this consumes time and labor.

SUMMARY OF THE INVENTION

10 The present invention was created in view of the above circumstances, and an object thereof is to provide a three-dimensional model management system which permits three-dimensional model data created by three-dimensional CAD to be utilized more effectively.

15 To achieve the above object, there is provided a three-dimensional model management system for managing a three-dimensional model in which relationship of subordination of individual parts is represented by a hierarchical structure. The three-dimensional model 20 management system comprises attribute information acquiring means for acquiring attribute information of individual parts constituting the three-dimensional model, sorting means for sorting the attribute information acquired by the attribute information acquiring means in accordance with the 25 hierarchical structure, display form setting means for setting a display form in which the attribute information is to be output for display, editing means for editing the

attribute information sorted by the sorting means, in accordance with settings by the display form setting means, and output means for outputting the attribute information edited by the editing means to a display device.

5 The above and other objects, features and advantages of the present invention will become apparent from the following description when taken in conjunction with the accompanying drawings which illustrate preferred embodiments of the present invention by way of example.

10

BRIEF DESCRIPTION OF THE DRAWINGS

FIG. 1 is a diagram illustrating the principle of operation according to the present invention;

15 FIG. 2 is a chart showing a hierarchical structure of a three-dimensional model stored in a storage device appearing in FIG. 1;

FIG. 3 shows a screen displayed as a result of processing of the three-dimensional model in FIG. 2, stored in the storage device;

20 FIG. 4 is a diagram illustrating a configuration according to an embodiment of the present invention;

FIG. 5 is a chart showing an example of a three-dimensional model processed by the embodiment shown in FIG. 4;

25 FIG. 6 is a flowchart showing an example of a process for displaying parts constituting a three-dimensional model and a 3D configuration view screen showing

a hierarchical structure of the parts;

FIG. 7 is a chart showing an example of display/non-display data;

FIG. 8 is a diagram showing an example of the 3D 5 configuration view screen;

FIG. 9 is a diagram showing how the 3D configuration view screen looks when a map part is right-clicked;

FIG. 10 is a diagram showing an example of how the 10 3D configuration view screen looks after the item "Non- display" is selected in a pop-up menu appearing in FIG. 9;

FIG. 11 is a diagram showing an example of how the 3D configuration view screen looks after rear cushion cover mold and plate are set to be non-displayed in the screen 15 shown in FIG. 10;

FIG. 12 is a diagram showing how the 3D configuration view screen looks when a display settings button is operated in the screen shown in FIG. 8;

FIG. 13 is a diagram showing an example of how the 20 3D configuration view screen looks after map parts alone are set to be displayed in the screen shown in FIG. 12;

FIG. 14 is a flowchart showing an example of a process executed when a display switching button is operated in the 3D configuration view screen;

25 FIG. 15 is a diagram showing an example of the 3D configuration view screen displayed before the display switching button is operated;

FIG. 16 is a diagram showing an example of the 3D configuration view screen displayed after the display switching button is operated;

5 FIG. 17 is a diagram showing an example of how the 3D configuration view screen looks after the item "Show All" is selected in a pop-up menu appearing in FIG. 16;

FIG. 18 is a diagram showing an example of display wherein the 3D configuration view screen and a PDM configuration view screen are arranged side by side;

10 FIG. 19 is a flowchart showing an example of a process for correlating a part shown in the 3D configuration view screen with the PDM configuration view screen;

FIG. 20 is a flowchart showing details of a "flat link process" appearing in FIG. 19;

15 FIG. 21 is a diagram showing an example of display wherein, in the PDM configuration view screen, rear suspension is right-clicked and link type is selected in a pop-up menu during execution of the process shown in FIG. 19;

20 FIG. 22 is a diagram showing how a part to be linked is selected from the 3D configuration view screen during execution of the process shown in FIG. 19;

25 FIG. 23 is a diagram showing an example of how the PDM configuration view screen looks after rear suspension is specified in the example shown in FIG. 22;

FIG. 24 is a chart showing an example of newly generated part data;

FIG. 25 is a flowchart showing details of a "multi-link process" appearing in FIG. 19;

FIG. 26 is a diagram showing an example of display wherein, in the PDM configuration view screen, rear 5 suspension is right-clicked and link type is selected in the pop-up menu during execution of the process shown in FIG. 19;

FIG. 27 is a diagram showing the PDM configuration view screen in which new items are created under rear 10 suspension;

FIG. 28 is a diagram showing an example of display wherein, in the 3D configuration view screen, rear cushion covers A and B are selected as parts to be linked;

FIG. 29 is a diagram showing an example of display 15 wherein rear cushion cover is selected as a target to which rear cushion covers A and B are to be linked;

FIG. 30 is a chart showing an example of newly generated part data;

FIG. 31 is a diagram showing an example of display 20 wherein link bar and spring are linked to link mechanism in the PDM configuration view screen;

FIG. 32 is a flowchart showing an example of a facet data generation process;

FIG. 33 is a diagram showing an example of display 25 wherein "Cover" is right-clicked in the PDM configuration view screen;

FIG. 34 is a diagram showing an example of facet

data generated by the process shown in the flowchart of FIG. 32;

FIG. 35 is a diagram illustrating a hierarchical structure specific to three-dimensional CAD;

5 FIG. 36 is a diagram showing a state in which a model shown in FIG. 35 is taken apart;

FIG. 37 is a diagram also illustrating a hierarchical structure specific to three-dimensional CAD;

10 FIG. 38 is a diagram showing a state in which a model shown in FIG. 37 is taken apart; and

FIGS. 39(A) and 39(B) are charts showing hierarchical structures of the model shown in FIG. 37, wherein FIG. 39(A) shows a hierarchical structure obtained when a part C is engaged using a part A as a reference part, 15 and FIG. 39(B) shows a hierarchical structure obtained when the part C is engaged using a part B as the reference part.

DESCRIPTION OF THE PREFERRED EMBODIMENTS

An embodiment of the present invention will be 20 hereinafter described with reference to the drawings.

FIG. 1 illustrates the principle of operation according to the present invention. In the figure, a storage device 1 stores a three-dimensional model 1a. A three-dimensional model management system 2 comprises 25 attribute information acquiring means 2a, sorting means 2b, display form setting means 2c, editing means 2d, and output means 2e. The management system acquires attribute

information from the three-dimensional model 1a stored in the storage device 1 to generate data for display and supplies the generated data to a display device 3 to be displayed thereby.

5 The attribute information acquiring means 2a acquires attribute information (e.g., part names) of individual parts constituting the three-dimensional model 1a.

10 The sorting means 2b sorts the attribute information acquired by the attribute information acquiring means 2a, in accordance with a hierarchical structure that the three-dimensional model has.

15 The display form setting means 2c sets a display form in which the attribute information sorted according to the hierarchical structure is to be output for display.

20 The editing means 2d edits the attribute information sorted by the sorting means 2b, in accordance with the settings by the display form setting means 2c.

25 The output means 2e outputs the attribute information edited by the editing means 2d to the display device 3.

30 The display device 3 comprises a CRT (Cathode Ray Tube) monitor or the like, for example, and displays an image signal output from the three-dimensional model management system 2.

35 Operation according to the illustrated principle will be now described.

40 Let it be assumed that a three-dimensional model

having a hierarchical structure shown in FIG. 2 is stored as the three-dimensional model 1a to be processed. In the figure, PT1, PT2, PT3-1, PT3-2, and PT4 to PT6 are part names (attribute information), and DM1 and DM2 represent 5 dummy parts which are used for purposes of the convenience of creating the three-dimensional model and which have no substance. PT3-1 and PT3-2 are registered as separate parts just for convenience' sake and constitute a single part in substance. Also, PT5 and PT6 are illustrated as if they are 10 subordinate to PT4, but this relationship of subordination is just for purposes of the convenience of drawing by CAD and PT4 to PT6 are actually in coordinate relationship.

The attribute information acquiring means 2a acquires the part names as the attribute information from 15 the three-dimensional model 1a stored in the storage device 1, and supplies the acquired part names to the sorting means 2b.

On receiving the part names acquired by the attribute information acquiring means 2a, the sorting means 20 2b sorts the part names in accordance with data (not shown) indicative of the hierarchical structure which the three-dimensional model 1a has. Specifically, the part names and the data indicative of the hierarchical structure are stored separately; therefore, these items of data are acquired and 25 then the part names are sorted. As a result, the part names are sorted as shown in FIG. 2.

The display form setting means 2c sets a display

form in which the part names sorted by the sorting means 2b are to be output for display. It is here assumed, for example, that the following three settings are made: (1) dummy parts are parts which do not actually exist and thus 5 are not displayed; (2) those parts which are separated for purposes of the convenience of design by CAD are unified; and (3) those parts which are in hierarchical relationship just because of the convenience of design by CAD are shown flat.

10 In accordance with the settings made by the display form setting means 2c, the editing means 2d edits the part names sorted according to the hierarchical structure. Specifically, in accordance with the setting (1), the dummy parts DM1 and DM2 are excluded from the 15 hierarchical structure. Also, in accordance with the setting (2), PT3-1 and PT3-2, which actually constitute a single part, are combined into one part and "PT3" is newly generated as a part name for the combined part. Further, in accordance with the setting (3), PT4 to PT6, which are 20 actually not in hierarchical relationship, are redefined as parts belonging to the same hierarchical level.

25 The part names edited by the editing means 2d are supplied to the output means 2e, which then converts the part names into image signal and outputs the signal to the display device 3 to be displayed thereby.

FIG. 3 shows an example of a screen displayed at the display device 3 as a result of the aforementioned

processing. Compared with FIG. 2, the dummy parts DM1 and DM2 are excluded as illustrated. Also, PT3-1 and PT3-2 are combined and shown as the single part PT3. Further, PT5 and PT6, which are apparently subordinate to PT4, are shown at 5 the same hierarchical level as PT4.

Thus, according to the present invention, the information peculiar to a three-dimensional model created by three-dimensional CAD can be edited and displayed in conformity with actual parts, making it possible to 10 immediately place an order for parts, for example, based on the displayed information.

Referring now to FIG. 4, an embodiment of the present invention will be described.

FIG. 4 is a block diagram illustrating a 15 configuration according to the embodiment of the present invention. As shown in the figure, a three-dimensional model management system 10 is connected via a network 12 to a bulk DB (Data Base) 13, an attribute DB 14, and a terminal unit 15. The management system manages three-dimensional 20 model data and attribute information stored in the bulk DB 13 and the attribute DB 14, respectively, and also supplies part of the data under its management to the terminal unit 15 after appropriately modifying same.

The three-dimensional model management system 10 25 comprises a CPU (Central Processing Unit) 10a, a ROM (Read Only Memory) 10b, a RAM (Random Access Memory) 10c, an HDD (Hard Disk Drive) 10d, a GC (Graphics Card) 10e, an I/F

(Interface) 10f, and a bus 10g.

The CPU 10a performs various arithmetic operations in accordance with programs stored in the HDD 10d etc. and also controls individual parts of the system.

5 The ROM 10b stores basic programs executed by the CPU 10a, data, etc.

The RAM 10c temporarily stores programs being executed by the CPU 10a, data derived in the middle of operations, etc.

10 The HDD 10d stores various programs and data.

The GC 10e performs operations in accordance with draw instructions supplied from the CPU 10a and converts an obtained image into a video signal, which is supplied to a display device 11.

15 The I/F 10f appropriately modifies the representation form of data when the data is exchanged with other devices through the network 12, and also performs control in accordance with a prescribed communication protocol.

20 The bus 10g interconnects the CPU 10a, ROM 10b, RAM 10c, HDD 10d, GC 10e and I/F 10f, and permits data to be exchanged between these elements.

25 The display device 11 comprises a CRT monitor or the like and displays the video signal supplied thereto from the GC 10e.

The network 12 is, for example, a LAN (Local Area Network), and allows data to be exchanged among the three-

dimensional model management system 10, the bulk DB 13, the attribute DB 14 and the terminal unit 15.

The bulk DB 13 stores bulk data, that is, actual data of three-dimensional models, separately in the form of 5 parts or units (hereinafter referred collectively as parts), for example. When a certain device makes a request for data, the bulk DB acquires the corresponding data and supplies same to the device through the network 12.

The attribute DB 14 stores attribute information 10 of individual parts constituting the three-dimensional models stored in the bulk DB 13, that is, information about part names, authors, creation dates, relationships of subordination with respect to other parts, etc.

The terminal unit 15 comprises a personal computer 15 or the like and is capable of making reference to the information on the three dimensional models which are under the management of the three-dimensional model management system 10.

Operation of the above embodiment will be now 20 described.

It is assumed that data of a three-dimensional model having a hierarchical structure shown in FIG. 5 is stored in the bulk DB 13 and the attribute DB 14. Specifically, actual data corresponding to individual parts 25 shown in the figure is stored in the bulk DB 13, and attribute information including part names of the individual parts, authors, creation dates, relationships of

subordination with respect to other parts, as well as storage locations, etc. is stored in the attribute DB 14.

With the above three-dimensional model stored, an operation may be performed to display a 3D configuration 5 view showing the three-dimensional configuration of the three-dimensional model, whereupon a process shown in the flowchart of FIG. 6 is executed. Upon start of the process shown in the flowchart, the following steps are executed.

[S1] The CPU 10a acquires attributes (part names 10 etc.) of the parts constituting the three-dimensional model from the attribute DB 14.

[S2] The CPU 10a acquires, from the attribute DB 14, display/non-display data indicating whether the individual parts are to be displayed or non-displayed.

15 FIG. 7 shows an example of the display/non-display data. In the illustrated example, "Display" is selected for all of "Map Part", which is a dummy part, "Mold", and "In-process Part" which denotes a part in process.

[S3] The CPU 10a controls the GC 10e to have a 20 window 60, shown in FIG. 8, displayed at the display device 11, and also looks up the display/non-display data shown in FIG. 7 to display those parts for which "Display" has been selected, in a display area 60f of the window 60.

25 In the example shown in FIG. 8, the window 60 entitled "3D Configuration View" is displayed. On the right side of the title bar is shown a display switching button 60a which is operated to switch contents of display. A

display settings button 60b, which is operated to set display contents, is shown to the right of the display switching button. To the right of the display settings button are shown buttons 60c to 60e which are operated to 5 minimize, maximize and close the window 60, respectively. Further, a chart showing the configuration of the parts corresponding to the one shown in FIG. 5 is displayed in the display area 60f beneath the title bar. Since, in this example, all of the parts are set to be displayed as shown 10 in FIG. 7, the display area 60f shows all parts.

[S4] If, with a certain item in the display area 60f specified with a mouse, not shown, the right mouse button is clicked (hereinafter right-clicked), the CPU 10a executes Step S5; if not, the flow returns and repeats Step 15 S4.

Let it be assumed that "Map Part A" is selected with a cursor 60g, as shown in FIG. 8, and then right-clicked. In this case, the decision in Step S4 becomes YES, and the flow proceeds to Step S5.

20 [S5] The CPU 10a has a pop-up menu displayed on screen.

FIG. 9 shows an example of a screen on which a pop-up menu 60h is displayed. In this example, the pop-up menu includes "Display" and "Non-display" as its selection 25 items.

[S6] If "Non-display" is selected in the pop-up menu 60h, the CPU 10a executes Step S7; otherwise the flow

proceeds to Step S8.

If "Non-display" is selected as shown in FIG. 9, Step S7 is executed.

[S7] The CPU 10a sets the corresponding item in 5 the display/non-display data to "Non-display".

In the example shown in FIG. 9, "Map Part A" has been selected; therefore, the CPU 10a judges from the attribute information associated with the selected part that this part has the attribute "Map Part", and thus sets the 10 map part in the display/non-display data shown in FIG. 7 to be non-displayed.

[S8] If "Display" is selected in the pop-up menu 60h, the CPU 10a executes Step S9; otherwise the flow proceeds to Step S10.

15 [S9] The CPU 10a sets the corresponding item in the display/non-display data to "Display".

[S10] The CPU 10a determines whether to continue the process or not. If the process is to be continued, the flow returns to Step S2 and the same process as described 20 above is repeated; if not, the process is ended.

If, in this example, the process is determined to be continued, the flow returns to Step S2, and since the map part in the display/non-display data has been set to be non-displayed, the display contents in the display area 60f are 25 updated in Step S3, so that a screen as shown in FIG. 10 is displayed. Specifically, as shown in the figure, "Map Part A" and "Map Part B", which are map parts, disappear from the

screen.

If "Rear Cushion Cover Mold", which is a mold, and "Plate", which is an in-process part, are thereafter selected and set to be non-displayed by a similar operation, 5 "Mold" and "In-process Part" in the display/non-display data shown in FIG. 7 are set to "Non-display", so that a screen as shown in FIG. 11 is displayed.

According to the process described above, data peculiar to three-dimensional CAD and data of in-process 10 parts can be excluded as needed from the screen. Accordingly, when reference is made to the three-dimensional model at a stage subsequent to design, for example, only the parts necessary for work can be selectively displayed.

In the example described above, an item displayed 15 in the display area 60f is directly selected and parts associated therewith are set to be displayed or non-displayed. Alternatively, as shown in FIG. 12, for example, a dialog box 60i may be displayed when the display settings button 60b is operated, so that the individual parts can be 20 checked for display or non-display. In the illustrated example, only the map part is checked ("Display" is selected); therefore, if an OK button 60j is operated with the map part selected, the map parts are displayed, so that a screen as shown in FIG. 13 is displayed. Namely, the map 25 parts A and B are displayed again.

In the above embodiment, parts having a specified attribute are collectively set to be displayed or non-

displayed, but each part may alternatively be set to be displayed or non-displayed. In this case, more detailed settings can be made, though the setting operation may require time.

5 A process executed when the display switching button 60a is operated, as shown in FIG. 15, will be now described with reference to FIG. 14. Upon start of the process shown in the flowchart of FIG. 14, the following steps are executed.

10 [S20] The CPU 10a has a pull-down menu displayed on screen, as shown in FIG. 16.

 In the illustrated example, a pull-down menu 60k displayed includes "Show All" and "Show Part" as its selection items.

15 [S21] If "Show All" is selected, the CPU 10a executes Step S22; otherwise the flow proceeds to Step S24.

 Since, in the example shown in FIG. 16, "Show All" is selected, the flow proceeds to Step S22.

20 [S22] The CPU 10a acquires the attributes of the three-dimensional model data from the attribute DB 14.

 [S23] The CPU 10a displays on screen the data of all parts acquired in Step S22.

 In this example, "Show All" has been selected, and accordingly, all parts are displayed in the display area 60f, 25 as shown in FIG. 17.

 [S24] If "Show Part" is selected, the CPU 10a executes Step S25; otherwise the flow returns to Step S21

and repeats the aforementioned process.

[S25] The CPU 10a acquires the attributes of the three-dimensional model data from the attribute DB 14.

[S26] The CPU 10a acquires the display/non-display data from the attribute DB 14.

[S27] The CPU 10a displays, in the display area 60f, parts other than those for which "Non-display" has been set.

If, while all parts are displayed with "Show All" selected, "Show Part" is selected, for example, parts are displayed again in accordance with the then settings of display/non-display data.

Flat link and multi-link will be now explained.

In the case of design by means of three-dimensional CAD, usually a product to be designed is divided into a plurality of sections and design is performed section by section. Parts designed in this manner are in many cases managed by PDM or the like so that reference can be made to the parts also from other divisions of the company.

Meanwhile, a three-dimensional model created by three-dimensional CAD often has a hierarchical structure generated just for the sake of convenience of drawing, and accordingly, it is generally not desirable that parts having such hierarchical structure be directly managed by PDM or the like. The following describes a method of appropriately converting the hierarchical structure when the three-dimensional model created by three-dimensional CAD is

registered in PDM.

Let it be assumed that, as shown in FIG. 18, a window 80 of a PDM configuration view showing a data structure managed by PDM and a window 90 of the 3D configuration view showing the data structure of the three-dimensional model are displayed on screen. With the windows displayed in this manner, a part appearing in the window 90 is correlated with the PDM configuration view shown in the window 80, and this process will be described with reference 10 to FIG. 19.

Upon start of the process shown in the flowchart of FIG. 19, the following steps are executed.

[S40] If, in the PDM configuration view screen (window 80), a certain display item is selected with the 15 mouse, not shown, and right-clicked, the CPU 10a executes Step S41; otherwise the flow returns and repeats Step S40.

If "Rear Suspension" in the window 80, for example, is selected and right-clicked, the flow proceeds to Step S41.

[S41] The CPU 10a has a pop-up menu displayed on 20 screen.

In this example, "Rear Suspension" has been selected, and a pop-up menu 80e including "Link Type" and "Request Approval" as its selection items is displayed near "Rear Suspension", as shown in FIG. 21.

25 [S42] If "Link Type" is selected in the pop-up menu 80e, the CPU 10a executes Step S43; otherwise the process is ended.

In the example shown in FIG. 21, "Link Type" is selected, and therefore, the flow proceeds to Step S43.

[S43] The CPU 10a has an additional pop-up menu displayed on screen.

5 In the example of FIG. 21, a pop-up menu 80f including "Flat Link" and "Multi-link" as its selection items is displayed near the pop-up menu 80e.

10 [S44] If "Flat Link" is selected in the pop-up menu 80f, the CPU 10a executes Step S45; otherwise the flow proceeds to Step S46.

In the example shown in FIG. 21, "Flat Link" is selected; therefore, the flow proceeds to Step S45.

15 [S45] The CPU 10a performs a flat link process in which a part having a hierarchical relationship specific to three-dimensional CAD is correlated flat with the PDM configuration view.

This process will be described in detail later with reference to FIG. 20.

20 [S46] If "Multi-link" is selected in the pop-up menu 80f, the CPU 10a executes Step S47; if not, the flow returns to Step S44 and repeats the aforementioned process.

25 [S47] The CPU 10a performs a multi-link process in which parts having a configuration specific to three-dimensional CAD are correlated in an integrated manner with the PDM configuration view.

Details of this process will be described later with reference to FIG. 25.

Referring now to FIG. 20, the "flat link process" appearing in FIG. 19 will be described in detail. In the process shown in the flowchart, a hierarchical structure which is generated just for the sake of convenience of 5 operation on three-dimensional CAD, such as those shown in FIGS. 37 to 39, is altered to be flat and correlated with the PDM configuration view. Upon start of the process shown in the flowchart, the following steps are executed.

[S60] The CPU 10a determines whether or not a part 10 to be linked has been specified in the 3D configuration view screen. If such a part has been specified, the flow proceeds to Step S61; if not, the flow returns and repeats Step S60.

If, for example, "Rear Suspension" is selected 15 with a cursor 100 in the 3D configuration view screen as the part to be linked, as shown in FIG. 22, the flow proceeds to Step S61.

[S61] The CPU 10a acquires the parts which are at 20 a lower hierarchical level than the specified part.

In the example shown in FIG. 22, "Rear Cushion", "Rear Cushion Cover", "Link Mechanism", "Link Bar" and "Spring", which are at a lower hierarchical level than "Rear Suspension", are acquired.

[S62] The CPU 10a rearranges the acquired parts 25 such that the parts are at an identical hierarchical level.

In the example of FIG. 22, "Link Bar" and "Spring" are rearranged so as to be at the same hierarchical level as

"Link Mechanism".

[S63] The CPU 10a has the group of the rearranged parts displayed in the PDM configuration view screen.

In this example, a screen as shown in FIG. 23 is 5 displayed. As illustrated, "Rear Cushion", "Rear Cushion Cover", "Link Mechanism", "Link Bar" and "Spring", appearing in FIG. 22, are rearranged at an identical hierarchical level and linked under "Rear Suspension".

[S64] The CPU 10a registers part data on the thus-10 linked parts anew in the attribute DB 14. The part data is attribute information indicating attributes of the individual parts included in the PDM configuration view.

An example of such part data is shown in FIG. 24. The part data shown in this example is one associated with 15 "Link Bar" appearing in FIG. 23. As illustrated in the figure, the part data includes "Part Name" indicating the name of the part, "Part No." indicating the management number of the part, "Author" indicating the name of a person who created the CAD data, "Creation Date" indicating the 20 date of creation of the data, "Reviser" indicating the name of a person who updated the data, "Last Update Date" indicating the date in which the data was last updated, "Link Type" indicating the type of link, "Storage Location" indicating the location where the data is stored, "Internal 25 Part Name" indicating the part name used within the three-dimensional CAD, "Material" indicating the material of the part, "Surface" indicating surface condition, and "Facet

Error" indicating an allowable error for the generation of facet data (described in detail later).

Specifically, "Link Bar" is set as the part name, "L15-12" as the part number, "Toru NAKAMOTO" as the author, 5 "99/12/10" as the creation date, "Kaoru TAKADA" as the reviser, "99/12/21" as the last update date, "Flat" as the link type, "A:/DATA" as the storage location, "LNK-12" as the internal part name, "Aluminum" as the material, the number "11" as the surface, and "10⁻⁶" as the facet error. 10 "Flat", which is stored as the link type, indicates that "Link Bar" is correlated by means of flat link. For ordinary correlation other than the flat link, "Dynamic" is stored, and in the case of the multi-link described later, "Multi" is stored.

15 According to the process described above, a hierarchical structure that is generated just for the sake of convenience of operation on three-dimensional CAD can be altered according to the hierarchical structure which the actual parts have and can be correlated with the PDM 20 configuration view.

Referring now to FIG. 25, the "multi-link process" appearing in FIG. 19 will be described in detail. In the process shown in the flowchart, parts which actually constitute a single part but are drawn as separate parts are 25 unified into one part and linked to the PDM configuration view. The process shown in the flowchart is executed upon selection of "Multi-link" in the pop-up menu 80f, as shown

in FIG. 26, which menu is displayed on selection of "Link Type" in the pop-up menu 80e displayed when a certain item is selected and right-clicked in the PDM configuration view screen. Upon start of the process, the following steps are 5 executed.

[S80] The CPU 10a determines whether or not a target of link has been specified in the 3D configuration view screen. If a target of link has been specified, the flow proceeds to Step S81; if not, the flow returns and 10 repeats Step S80.

If, in the 3D configuration view screen shown in FIG. 26, "Rear Suspension" is selected with the cursor 100 as the target of link, for example, the flow proceeds to Step S81.

15 [S81] If a request to create a new item is made in the PDM configuration view screen, the CPU 10a executes Step S82; if not, the flow returns and repeats Step S81.

For example, if a request is made to create a new item under "Rear Suspension" in the screen shown in FIG. 26 20 (e.g., "Create New Item" is selected in a pop-up menu, not shown), the flow proceeds to Step S82.

[S82] The CPU 10a performs a process of creating a new item in the PDM configuration view screen.

As shown in FIG. 27, for example, a process of 25 creating new items "Rear Cushion", "Rear Cushion Cover" and "Link Mechanism" under "Rear Suspension" is executed.

[S83] If parts to be linked are specified in the

3D configuration view screen, the CPU 10a executes Step S84; if not, the flow returns and repeats Step S83.

If, for example, "Rear Cushion Cover A" and "Rear Cushion Cover B" are specified in the 3D configuration view screen, as shown in FIG. 28, the flow proceeds to Step S84. "Rear Cushion Cover A" and "Rear Cushion Cover B" are parts which actually constitute one part but were created as two separate parts for purposes of the convenience of drawing by CAD. For example, the rear cushion covers A and B are symmetrical parts and were created by first creating the rear cushion cover A and then the rear cushion cover B by inverting a copy of the cover A.

[S84] If a certain item has been specified in the PDM configuration view screen as a target of link, the CPU 10a executes Step S85; if not, the flow returns and repeats Step S84.

[S85] The CPU 10a maps the parts specified in the 3D configuration view screen, into the PDM configuration view screen.

In the above example, if "Rear Cushion Cover" in the PDM configuration view screen, for example, is selected with the cursor 100 as the target to which the rear cushion covers A and B are to be linked, as shown in FIG. 29, the rear cushion covers A and B are mapped into the PDM configuration view screen in association with "Rear Cushion Cover".

[S86] The CPU 10a registers part data on the thus-

linked parts anew in the attribute DB 14.

In this example, part data as shown in FIG. 30 is registered anew in the attribute DB 14.

In the illustrated example, "Multi" is set as the 5 link type, indicating that the parts concerned are linked by means of multi-link. Also, as seen from the inclusion of two sets of the items "Storage Location" through "Surface", the attribute information about the two parts, that is, the rear cushion covers A and B, is stored in a unified manner. 10 Further, the part name "Rear Cushion Cover" is assigned to the unification of the two parts.

[S87] The CPU 10a determines whether to continue the process or not. If the process is to be continued, the flow returns to Step S83 to repeat the aforementioned 15 process; if not, the process is ended.

For example, assuming that the process is continued, if the parts "Link Bar" and "Spring" are specified in the 3D configuration view screen and then the item "Link Mechanism" is specified with the cursor 100 as 20 the target of link, as shown in FIG. 31, the link bar and the spring are correlated with the link mechanism and part data including these two parts is created.

According to the process described above, even in cases where parts which actually constitute a single part 25 are created separately for purposes of the convenience of operation on three-dimensional CAD, they can be correlated as a single part with the PDM configuration view screen.

Also, in this case, the parts included in the individual items shown in the PDM configuration view screen can be identified by making reference to the part data.

A process of generating facet data will be now 5 described. After the creation of a three-dimensional model is completed, it is necessary that the finished three-dimensional model be presented for view to a supervisor or the like to obtain his/her approval. The supervisor's terminal unit may not have a three-dimensional CAD 10 application program installed therein, and it is therefore desirable that the three-dimensional model be viewed without such an application program. Accordingly, in this embodiment, the three-dimensional model is converted to facet data composed of polygons and texture so that it can 15 be viewed with ease. In the following, a process of generating facet data from the part for which approval is requested will be described with reference to FIG. 32.

Upon start of the process shown in the flowchart of FIG. 32, the following steps are executed.

20 [S100] If a certain item is selected in the PDM configuration view screen, the CPU 10a executes Step S101; if not, the flow returns and repeats Step S100.

If "Cover", for example, is selected in the PDM configuration view screen shown in FIG. 33, the flow 25 proceeds to Step S101.

[S101] The CPU 10a has a pop-up menu displayed on screen.

In this example, the pop-up menu 80e is displayed near the selected item "Cover".

[S102] If "Request Approval" is selected in the pop-up menu 80e, the CPU 10a executes Step S103; if not, the 5 process is ended.

If, in the pop-up menu 80e, "Request Approval" is selected, the flow proceeds to Step S103.

[S103] The CPU 10a acquires actual data of the corresponding three-dimensional model from the bulk DB 13. 10 Specifically, the CPU 10a acquires the part data (cf. FIG. 24) corresponding to the selected item from the attribute DB 14, and identifies the storage location and filename of the actual data of the corresponding three-dimensional model. Subsequently, the CPU acquires the actual data of the target 15 three-dimensional model from the bulk DB 13.

In this example, first, the part data associated with "Cover" is acquired from the attribute DB 14, and then the actual data of the corresponding three-dimensional model is acquired from the bulk DB 13.

20 [S104] The CPU 10a acquires the surface information, material information and facet error included in the part data.

[S105] The CPU 10a converts the acquired actual data to facet data.

25 This conversion process can be carried out by dividing the three-dimensional model into a plurality of polygonal regions by making reference to the facet error,

and applying to each polygonal region a texture conforming to the surface information and the material information.

[S106] The CPU 10a generates identification seal information and affixes the generated information to the 5 facet data generated in Step S105. The identification seal information is data composed of the name of a person in charge and a date.

[S107] The CPU 10a sends the generated facet data to the bulk DB 13 to be stored therein.

10 [S108] The CPU 10a locks the generated facet data and the actual data for which approval has been requested, so that the data may not be altered.

15 FIG. 34 shows an example of the facet data generated by the aforementioned process. In the example illustrated in the figure, facet data 120a showing the part "Cover" is displayed at the center of a drawing 120, and the identification seal information showing the name of a person in charge and the date is affixed to the lower right corner of the drawing.

20 Since the facet data is composed of polygons and texture, it is possible to create a suitable drawing of the part as viewed from any desired direction.

25 According to the embodiment described above, a three-dimensional model generated by three-dimensional CAD can be presented for view with ease.

In the foregoing embodiment, explanation is made of the case where parts shown in the 3D configuration view

screen are correlated with the PDM configuration view screen, by way of example. Alternatively, alteration of the hierarchical structure may be instructed when the 3D configuration view screen is to be displayed, so that the 3D 5 configuration view screen may be shown in accordance with the instruction.

The above-described processing functions can be performed by a computer. In this case, the contents of the functions to be accomplished by the three-dimensional model 10 management system are described in a program recorded in a computer-readable recording medium. By executing the program by a computer, it is possible to perform the above-described processing. The computer-readable recording medium includes magnetic recording device, semiconductor 15 memory and the like. To distribute the program to the market, the program may be stored in portable recording media such as CD-ROMs (Compact Disk Read Only Memories) or floppy disks. Alternatively, the program may be stored in a storage device of a computer connected to a network and may 20 be transferred to other computers through the network. To execute the program by a computer, the program stored in a hard disk unit or the like of the computer is loaded into the main memory and executed.

As described above, according to the present 25 invention, a three-dimensional model management system for managing a three-dimensional model in which relationship of subordination of individual parts is represented by a

hierarchical structure comprises attribute information acquiring means for acquiring attribute information of individual parts constituting the three-dimensional model, sorting means for sorting the attribute information acquired 5 by the attribute information acquiring means in accordance with the hierarchical structure, display form setting means for setting a display form in which the attribute information is to be output for display, editing means for editing the attribute information sorted by the sorting 10 means, in accordance with settings by the display form setting means, and output means for outputting the attribute information edited by the editing means to a display device. It is therefore possible to display a configuration view screen showing a near-real configuration, without being 15 influenced by a hierarchical structure etc. peculiar to a three-dimensional model generated by three-dimensional CAD.

The foregoing is considered as illustrative only of the principles of the present invention. Further, since numerous modifications and changes will readily occur to 20 those skilled in the art, it is not desired to limit the invention to the exact construction and applications shown and described, and accordingly, all suitable modifications and equivalents may be regarded as falling within the scope 25 of the invention in the appended claims and their equivalents.

WHAT IS CLAIMED IS:

1. A three-dimensional model management system for managing a three-dimensional model in which relationship of subordination of individual parts is represented by a 5 hierarchical structure, comprising:

attribute information acquiring means for acquiring attribute information of individual parts constituting the three-dimensional model;

10 sorting means for sorting the attribute information acquired by said attribute information acquiring means in accordance with the hierarchical structure;

display form setting means for setting a display form in which the attribute information is to be output for display;

15 editing means for editing the attribute information sorted by said sorting means, in accordance with settings by said display form setting means; and

output means for outputting the attribute information edited by said editing means to a display device.

20
2. The three-dimensional model management system according to claim 1, wherein said editing means excludes attribute information of a predetermined part such that the predetermined part is not displayed on a display screen of 25 the display device.

3. The three-dimensional model management system

according to claim 1, further comprising classifying means for classifying the attribute information acquired by said attribute information acquiring means according to attributes,

5 wherein said editing means refers to a result of classification by said classifying means and excludes attribute information of a part having a predetermined attribute such that said part is not displayed on a display screen of the display device.

10

4. The three-dimensional model management system according to claim 1, wherein said editing means rearranges attribute information of a part at a lower hierarchical level than a predetermined hierarchical level in the 15 hierarchical structure of the three-dimensional model such that said part belongs to the predetermined hierarchical level.

5. The three-dimensional model management system 20 according to claim 1, further comprising redefining means for redefining, as a single part, a group of parts which are defined in the three-dimensional model as a plurality of parts, and for generating anew attribute information on the redefined part.

25

6. The three-dimensional model management system according to claim 5, wherein said redefining means

redefines a predetermined part to which a plurality of parts are subordinate at a lower hierarchical level, as a single part including said plurality of parts, and generates anew attribute information on the redefined part.

5

7. The three-dimensional model management system according to claim 1, further comprising specifying means for specifying predetermined attribute information displayed by the display device,

10 three-dimensional data acquiring means for acquiring, from the three-dimensional model, three-dimensional data corresponding to the attribute information specified by said specifying means, and

15 facet data generating means for generating facet data, which is surface data for display, from the three-dimensional data acquired by said three-dimensional data acquiring means.

8. The three-dimensional model management system
20 according to claim 7, further comprising identification information affixing means for affixing identification information indicative of normal creation to the facet data generated by said facet data generating means.

25 9. A computer-readable recording medium recording a program for causing a computer to manage a three-dimensional model in which relationship of subordination of

individual parts is represented by a hierarchical structure, wherein the program causes the computer to function as

attribute information acquiring means for acquiring attribute information of individual parts 5 constituting the three-dimensional model,

sorting means for sorting the attribute information acquired by the attribute information acquiring means in accordance with the hierarchical structure,

display form setting means for setting a display 10 form in which the attribute information is to be output for display,

editing means for editing the attribute information sorted by the sorting means, in accordance with settings by the display form setting means, and

15 output means for outputting the attribute information edited by the editing means to a display device.

ABSTRACT OF THE DISCLOSURE

A three-dimensional model management system wherein a hierarchical structure and data peculiar to a three-dimensional model created by three-dimensional CAD are 5 excluded to display a configuration view screen showing a configuration close to that of an actual object. Attribute information acquiring unit of the three-dimensional model management system acquires part names, as attribute information, from a three-dimensional model stored in a 10 storage device. Sorting unit sorts the acquired part names in accordance with a hierarchical structure which the three-dimensional model has. Display form setting unit makes settings such that, for example, dummy data which is used for the sake of convenience of design and has no substance 15 is not displayed on screen. Editing unit edits the part names sorted by the sorting unit, in accordance with the settings made by the display form setting unit. Output unit supplies the part names edited by the editing unit to a display device to be displayed thereby.




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6

PART NAME	DISPLAY/NON-DISPLAY
MAP PART	DISPLAY
MOLD	DISPLAY
IN-PROCESS PART	DISPLAY

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23

Part Name	Part No.	Author	Creation Date	Reviser	Last Update Date
Link Bar	L15-12	Toru NAKAMOTO	99/12/10	Kaoru TAKADA	99/12/21

Link Type	Storage Location	Internal Part Name	Material	Surface	Facet Error
Flat	A:/DATA	LNK-12	Aluminum	11	10^{-6}

FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29

Part Name	Part No.	Author	Creation Date	Reviser	Last Update Date
Rear Cushion Cover	R14-13	Toru NAKAMOTO	99/12/10	Kaoru TAKADA	99/12/21

Link Type	Storage Location	Internal Part Name	Material	Surface
Multi	A:/DATA3	Rear Cushion Cover A	Urethane	11

Storage Location	Internal Part Name	Material	Surface	Facet Error
A:/DATA4	Rear Cushion Cover B	Urethane	1 1	10 ⁻⁶

FIG. 30




FIG. 31




FIG. 32





FIG. 33

120



120b

Person in Charge: Takeshi NAKAKOUCHI

Date: Dec. 10, 1999

FIG. 34




FIG. 35
PRIOR ART




FIG. 36
PRIOR ART




FIG. 37
PRIOR ART




FIG. 38
PRIOR ART




FIG. 39(A)
PRIOR ART




FIG. 39(B)
PRIOR ART

Declaration and Power of Attorney For Patent Application

特許出願宣言書及び委任状

Japanese Language Declaration

日本語宣言書

下記の氏名の発明者として、私は以下の通り宣言します。

As a below named inventor, I hereby declare that:

私の住所、私書箱、国籍は下記の私の氏名の後に記載された通りです。

My residence, post office address and citizenship are as stated next to my name.

下記の名称の発明に関して請求範囲に記載され、特許出願している発明内容について、私が最初かつ唯一の発明者（下記の氏名が一つの場合）もしくは最初かつ共同発明者であると（下記の名称が複数の場合）信じています。

I believe I am the original, first and sole inventor (if only one name is listed below) or an original, first and joint inventor (if plural names are listed below) of the subject matter which is claimed and for which a patent is sought on the invention entitled

THREE-DIMENSIONAL MODEL MANAGEMENT

SYSTEM

上記発明の明細書（下記の欄でx印がついていない場合は、本書に添付）は、

the specification of which is attached hereto unless the following box is checked:

一月一日に提出され、米国出願番号または特許協定条約国際出願番号を _____ とし、
(該当する場合) _____ に訂正されました。

was filed on _____
as United States Application Number or
PCT International Application Number
_____ and was amended on
_____ (if applicable).

私は、特許請求範囲を含む上記訂正後の明細書を検討し、内容を理解していることをここに表明します。

I hereby state that I have reviewed and understand the contents of the above identified specification, including the claims, as amended by any amendment referred to above.

私は、連邦規則法典第37編第1条56項に定義されるとおり、特許資格の有無について重要な情報を開示する義務があることを認めます。

I acknowledge the duty to disclose information which is material to patentability as defined in Title 37, Code of Federal Regulations, Section 1.56.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

Japanese Language Declaration (日本語宣言書)

私は、米国法典第35編119条(a)-(d)項又は365条(b)項に基き下記の、米国以外の国の少なくとも一ヵ国を指定している特許協力条約365条(a)項に基く国際出願、又は外国での特許出願もしくは発明者証の出願についての外国優先権をここに主張するとともに、優先権を主張している、本出願の前に出願された特許または発明者証の外国出願を以下に、特内をマークすることで、示しています。

Prior Foreign Application(s)

外国での先行出願

11-336195
(Number)
(番号)

Japan
(Country)
(国名)

(Number)
(番号)

(Country)
(国名)

私は、第35編米国法典119条(e)項に基いて下記の米国特許出願規定に記載された権利をここに主張いたします。

(Application No.)
(出願番号)

(Filing Date)
(出願日)

私は、下記の米国法典第35編120条に基いて下記の米国特許出願に記載された権利、又は米国を指定している特許協力条約365条(c)に基く権利をここに主張します。また、本出願の各請求範囲の内容が米国法典第35編112条第1項又は特許協力条約で規定された方法で先行する米国特許出願に開示されていない限り、その先行米国出願書提出日以後で本出願書の日本国内または特許協力条約国提出日までの期間中に入手された、連邦規則法典第37編1条5.6項で定義された特許資格の有無に関する重要な情報について開示義務があることを認識しています。

(Application No.)
(出願番号)

(Filing Date)
(出願日)

(Application No.)
(出願番号)

(Filing Date)
(出願日)

私は、私自身の知識に基いて本宣言書中で私が行なう表明が真実であり、かつ私の入手した情報と私の信じるところに基く表明が全て真実であると信じていること、さらに故意になされた虚偽の表明及びそれと同様の行為は米国法典第18編第1001条に基ぎ、罰金または拘禁、もしくはその両方ににより処罰されること、そしてそのような故意による虚偽の表明を行なえば、出願した、又は既に許可された特許の有効性が失われることを認識し、よってここに上記のごく宣言を致します。

I hereby claim foreign priority under Title 35, United States Code, Section 119(a)-(d) or 365(b) of any foreign application(s) for patent or inventor's certificate, or 365(a) of any PCT International application which designated at least one country other than the United States, listed below and have also identified below, by checking the box, any foreign application for patent or inventor's certificate, or PCT International application having a filing date before that of the application on which priority is claimed.

Priority Not Claimed
優先権主張なし

26/11/1999
(Day/Month/Year Filed)
(出願年月日)



(Day/Month/Year Filed)
(出願年月日)



I hereby claim the benefit under Title 35, United States Code, Section 119(e) of any United States provisional application(s) listed below.

(Application No.)
(出願番号)

(Filing Date)
(出願日)

I hereby claim the benefit under Title 35, United States Code, Section 120 of any United States application(s), or 365(c) of any PCT International application designating the United States, listed below and, insofar as the subject matter of each of the claims of this application is not disclosed in the prior United States or PCT International application in the manner provided by the first paragraph of Title 35, United States Code Section 112, I acknowledge the duty to disclose information which is material to patentability as defined in Title 37, Code of Federal Regulations, Section 1.56 which became available between the filing date of the prior application and the national or PCT International filing date of application.

(Status: Patented, Pending, Abandoned)
(現況: 特許許可済、係属中、放棄済)

(Status: Patented, Pending, Abandoned)
(現況: 特許許可済、係属中、放棄済)

I hereby declare that all statements made herein of my own knowledge are true and that all statements made on information and belief are believed to be true; and further that these statements were made with the knowledge that willful false statements and the like so made are punishable by fine or imprisonment, or both, under Section 1001 of Title 18 of the United States Code and that such willful false statements may jeopardize the validity of the application or any patent issued thereon.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

Japanese Language Declaration
(日本語宣言書)

委任状： 私は下記の発明者として、本出願に関する一切の手続を米特許商標局に対して遂行する弁理士または代理人として、下記の者を指名いたします。（弁護士、または代理人の氏名及び登録番号を明記のこと）

POWER OF ATTORNEY: As a named inventor, I hereby appoint the following attorney(s) and/or agent(s) to prosecute this application and transact all business in the Patent and Trademark Office connected therewith (list name and registration number)

James D. Halsey, Jr., 22,729; Harry John Staas, 22,010; David M. Pitcher, 25,908; John C. Garvey, 28,607; J. Randall Beckers, 30,358; William F. Herbert, 31,024; Richard A. Gollhofer, 31,106; Mark J. Henry, 36,162; Gene M. Garner II, 34,172; Michael D. Stein, 37,240; Paul I. Kravetz, 35,230; Gerald P. Joyce, III, 37,648; Todd E. Marlette, 35,269; Harlan B. Williams, Jr., 34,756; George N. Stevens, 36,938; Michael C. Soldner, P-41,455 and William M. Schertler, 35,348 (agent)

書類送付先

Send Correspondence to:

STAAS & HALSEY
700 Eleventh Street, N.W.
Suite 500
Washington, D.C. 20001

直接電話連絡先 (名前及び電話番号)

Direct Telephone Calls to: (name and telephone number)

STAAS & HALSEY
(202) 434-1500

唯一または第一発明者名		Full name of sole or first inventor	
		Makoto FUJIEDA	
発明者の署名	日付	Inventor's signature	Date
		Makoto Fujieda	
住所	Residence		
Kawasaki, Japan			
国籍	Citizenship		
Japanese			
私書箱	Post Office Address		
c/o FUJITSU LIMITED.			
1-1, Kamikodanaka 4-chome, Nakahara-ku, Kawasaki 211-8588 Japan			
第二共同発明者			
Full name of second joint inventor, if any			
第二共同発明者	日付	Second inventor's signature	Date
住所	Residence		
国籍	Citizenship		
私書箱	Post Office Address		

(第三以降の共同発明者についても同様に記載し、署名をすること)

(Supply similar information and signature for third and subsequent joint inventors.)